

DragonFlyBSD - Bug #2624

Atheros AR9460 list scan shows nothing

01/07/2014 01:24 AM - herrgard

Status: Closed	Start date: 01/07/2014
Priority: Normal	Due date:
Assignee:	% Done: 0%
Category:	Estimated time: 0.00 hour
Target version:	
Description dragonfly x86_64, jan 6 snapshot. # ifconfig wlan0 list scan shows nothing. The card is not detected pre matt's recent ath upgrade. Card works in freebsd 10 rc. It worked one time (out of maybe the 50 times I have tried). I did nothing special to make it work then. I have these atheros related messages on console on boot: ar9300_freebsd_setup_x_tx_desc: called, 0x0/0, 0x0/0, 0x0/0 ar9300_Stub_GetCTSTimeout: called ar9300_Stub_GetCTSTimeout: called ar9300_Stub_GetAntennaSwitch: called ar9300_Stub_GetAntennaSwitch: called	

History

#1 - 08/18/2015 02:55 PM - herrgard

- Status changed from New to Closed

This works nowadays. I don't know what commit, but probably one of the ath driver syncs from freebsd.